



**Chicony Electronics Co., Ltd.**

<b>DEPARTMENT</b>	<b>UVC Like driver</b> Release Notes	<b>DATE: 8. 10, 2007</b>
<b>CM NBC RD</b>		<b>PAGE: 1 of 2</b>

# **UVC Like driver**

## **Release Notes**

For  
**CNF6041**

Chicony Electronics Company Ltd.  
Camera Module BU

<b>DEPARTMENT</b>	<b>UVC Like driver</b> Release Notes	<b>DATE: 8. 10, 2007</b>
<b>CM NBC RD</b>		<b>PAGE: 2 of 2</b>

## Release Notes

<b>Date</b>	<b>Version</b>	<b>Modification</b>
03,21,2007	5.7.25.0	<ol style="list-style-type: none"> <li>1.Fix after install driver and restart NB,OS will pop up a message of "find new hardware" issue</li> <li>2.Modify INF file. Change the "Detect Power line Frequency" function from "Run once" to "Run"</li> </ol>
04,03,2007	5.7.25.400	<ol style="list-style-type: none"> <li>1.Modify Device name "Acer Crystal Eye webcam"</li> </ol>
04,04,2007	5.7.26.400	<ol style="list-style-type: none"> <li>1. New driver release(including Multi-Language : CHS · CHT · Danish · Dutch · Finnish · French · English · German · Italian · Japanese · Korean · Norwegian · Portuguese (Brazilian) · Portuguese (Portugal) · Spanish · Swedish)</li> <li>2. WHQL Approved for XP</li> </ol>
04,26,2007	5.7.28.400	<ol style="list-style-type: none"> <li>1.Fix Arcade Software installshield hang up issue</li> <li>2. WHQL Approved for XP32/XP64 and Vista32/64</li> </ol>
08,06,2007	5.7.31.400	<ol style="list-style-type: none"> <li>1.Fix preview Lag issue.</li> <li>2. WHQL Approved for XP32/XP64 and Vista32/64</li> </ol>